

FIELD INSPECTION REPORT

Date of Inspection : 08/01/2021		District: W. Champaran	
Division : Bettiah		Length (km): 1.5 km	
Name of the Road: P24 to Brahman tolan tola			
Scheme/Programme: MAINTENANCE		Road Id No.: 31808801833	
Package No.: LT NSY		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Upgradation/ Maintenance			
Sl. No.	Particulars to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature
(Signature)

NAME:

DESIGNATION: