


FIELD INSPECTION REPORT

Date of Inspection : 03/01/2021		District : Munger	
Division : Munger		Length (km): 0.687	
Name of the Road : Mahua Tree to Bhikakita Path			
Scheme/Programme : MAINTENANCE		P.M.G.S.Y	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl.No.	Parameters to be checked		Remarks
1	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes / No N/A
f)	Contraction Joints provided or not(CC Pavement)		Yes / No N/A
g)	Compaction of flank/slope & raincuts if any		Yes / No
2	Cross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U N/A
b)	Condition of Abutment & Wing walls Slab in Rcc culverts		S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges		S/SRI/U N/A
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes / No
4	Compliance Histroy		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	✓	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		


 (Signature) 03/01/2021

NAME :

MD. Altaf Anwar

DESIGNATION :

J.E.