

FIELD INSPECTION REPORT

Date of Inspection: 3/11/21 District: Aurangabad
 Division: Aurangabad Length (km): 1.9
 Name of the Road: Maigra at Bara Road to Anabir Simri
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/E
b)	Condition of Surfacing	S S/E
c)	Binding On dirt	S S/U
d)	Road Camber	S S/E
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Contraction of flank slope & rinecuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

✓ Satisfactory (S)
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

S

NAME: Yugeswar Kumar Singh

Executive Engr.
 R.W.D. Division
 Aurangabad