



FIELD INSPECTION REPORT

Date of Inspection : 3-12-20	District: Aurangabad
Division : Aurangabad	Length (km): 1.90 Km
Name of the Road: 709 to Kushalees	
Scheme/Programme: MAINTENANCE	
Package No.: BRD2R-699	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No Yes/No
f)	Contraction Joints provided or not (CC Pavement)	yes Yes/No
g)	Compaction of flank/slope & raincuts if any	yes Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its parapets	SRI S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRI S/SRI/U
c)	Condition of railings/slab/approach for Bridges	— S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones Pavement road markings are provided and maintained	200m yes Yes/No
4.	Compliance History Maintenance Record not found	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 3.12.20
 (Signature)


NAME: