Name: Ashck kimor

Desigination $\sigma \mathcal{E}$

Date O	District Blog pur	w.
MOTSTATO	PIRO Length (km):	1.635
rvaine c	Name of the Road: Too to Koshikay	
Scheme	ramme MAINTENANCE	
State No.:	e No.: Road Id No.: 10401801909	09
Wall C	Worl: Ongoing/Completeted/Under Maintenance	
SI NO IN IS	New Connectivity/Up gradation/Maintenance	
or No.	Parameters to be checked	Remarks
-	Pavment	
a)	Road Junction condition	N/S
b)	Condition of Surfacing	7/5/
c)	Riding Quality	3/0
٥	Road Camber	NS
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Xes/No
Ď	Contraction Joints provided or not (CC Pavement)	Yes/No
<u>e</u>)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	,8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	&/SRI/U
c)	Condition of railings/slab/approach for Bridges	SISRIVU
	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Xes/No
	Compliance History	
a) 9	Status of ATR's & any others	

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)