


FIELD INSPECTION REPORT

Date of Inspection : 05.01.2021		District : East Champaran	
Division : Chakla		Length (Km): 1.570 1.570	
Name of the Road : NH-104 Bhardenya Kame Tola to Bhardenya Mughan			
Scheme/Programme : TOL		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance ☒	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance ☒	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S	
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)	S	
g)	Compaction of flank/slope & raincuts if any	S	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	-	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-	
c)	Condition of railings/slab/approach for Bridges	-	
3.	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	S	
4.	Compliance History		
a)	Status of ATR's & any others	-	

Overall Rating :	Satisfactory (S)	S
	Satisfactory but requires improvement (SRI)	-
	Unsatisfactory (U)	-


 (Signature) 7/1/20
 J. C. Jha

NAME :
 DESIGNATION :