

FIELD INSPECTION REPORT

Date of Inspection : 5-01-2023 District: Garoah
 Division : Patkoti Length (km):
 Name of the Road: Sharma Chowk to Garday Eiman via Horizontala
 Scheme/Programme: MAINTENANCE Road Id No.:
 Package No.:
 Status of the Project: Ongoing Completed/Under Maintenance Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU S
b)	Condition of Surfacing	SU S
c)	Riding Quality	SU S
d)	Road Camber	SU S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No S
g)	Compaction of flank slope & raincuts if any	Yes/No S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No S
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


 05/01/2023
 (Signature)

NAME: Asay Kumar Singh

DESIGNATION: