


### FIELD INSPECTION REPORT

Date of Inspection:- 6-1-21		District:- Sheohar.
Division:- RWD, Works Div. Sheohar		Length (km):- 0.350 Km
Name of the Road:- Nayagan Pulkha Nikot to Harijattola Mahadev Ram		
Scheme/Programme:- MAINTENANCE M MGSY SC		
Package No.:-		Road Id No.:-
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	Only G.S.B in S/U ✓
b)	Condition of Surfacing	Exposed foot stone S/U ✓
c)	Riding Quality	S/U
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No Not Done
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railing/slab/approach for bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Name:- Dillip Kumar

  
 (Signature)

DESIGNATION:- Junior Engineer