

FIELD INSPECTION REPORT

Date of Inspection : 07.01.2021	District: Murgehgaon
Division: Mur - East - 2	Length (km):
Name of the Road: LOZG-TOI Bangalore PWD road to Mantoli Haskamanshi	
Scheme/Programme: MAINTENANCE	PMU/SSY
Package No.: BR-23R-459.	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No provision of c.c. pavement
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No Some raincut found
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U No any slab culverts.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Require maintainan
4.	Compliance History	
a)	Status of ATR's & any others	x

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Shoulders and Road Furniture require to be maintain.

(Signature) 07.01.2021

NAME: Kamte Dd. Singh

DESIGNATION: JE