

FIELD INSPECTION REPORT

Date of Inspection: 26/01/2021	District: Dharmapuri	
Division: Danduragi	Length (km): 0.840 km	
Name of the Road: Bajah Path to Hassanpur		
Scheme Programme: MAINTENANCE		
Package No: 1	Road Id No: 1	
Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance		
Work is a case of: ☒ New Connectivity ☐ Up gradation ☐ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & cutouts if any	Yes/No
2.	Drainage	
a)	Condition of head walls in flume pipe culverts including its painting	S/SRU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU
c)	Condition of railings/slab approach for Bridges	S/SRU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/lan & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance of ATR	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Pawan Kumar Singh

DESIGNATION: J-1