

FIELD INSPECTION REPORT

Date of Inspection : 07/01/24		District: East Champaran	
Division : Kosi		Length (km): 0.533	
Name of the Road: 701 Mirza Tola to Pathmukh village Mirza			
Scheme/Programme: MAINTENANCE		Road Id No.: 3170850125	
Package No.:			
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/UP gradation/ Maintenance	
Sl. No.		Parameters to be checked	
1. Pavement			
a) Road Junction condition		S/U	
b) Condition of Surfacing		S/U	
c) Riding Quality		S/U	
d) Road Camber			
c) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	
f) Contraction Joints provided or not (CC Pavement)		Yes/No	
g) Compaction of Flank/slope & raincuts if any		Yes/No	
2. Cross Drainage			
a) Condition of head walls in Flume pipe culverts including its painting		S/SR/U	
b) Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U	
c) Condition of railings/slab/approach for Bridges		S/SR/U	
3. Road Furniture			
a) Whether sign boards/informatory/cautionary. Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
4. Compliance History			
a) Status of ATR's & any others		N.A.	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:

Milind Kumar Singh

DESIGNATION:

Junior Engineer, Kosi

07/01/24