

FIELD INSPECTION REPORT

Date of Inspection : 3.12.20	District: Amargol
Division : Amargol	Length (km): 0.850 km
Name of the Road: T9 to Baligigla	
Scheme/Programme:	MAINTENANCE
Package No.: BRD2R-751	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Surface condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes Yes/No
f)	Construction Joints provided or not (CC Pavement)	yes Yes/No
g)	Compaction of flank/slope & raincuts if any	No Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	- S/SRI/U
c)	Condition of railings/slab/approach for Bridges	- S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones Pavement road markings are provided and maintained	yes Yes/No
4.	Compliance History	Flame not maintained
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

3.12.20
AE
[Signature]

NAME: