

FIELD INSPECTION REPORT

Date of Inspection: 3.12.20	District: Aurangabad
Division: Aurangabad	Length (km): 0.500 km
Name of the Road: L112-T09 to Pant	
Scheme/Programme:	MAINTENANCE
Package No.: BRD 2R-757	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No Yes/No
f)	Contraction Joints provided or not (CC Pavement)	No Yes/No
g)	Compaction of flank/slope & raincuts if any	No Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its p	yes S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	yes S/SRI/U
c)	Condition of railings/slab/approach for Bridges	- S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	yes
4.	Compliance History	Maintenance Board not found
a)	Status of ATR's & any others	Raincut found near HPC at 0.00m

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

3.12.20
AE
(Signature)

NAME: