


FIELD INSPECTION REPORT

Date of Inspection :	2.12.20	District:	Aurangabad
Division :		Length (km):	0.740 work done - 0.600 km
Name of the Road:	LSD 4 - TO 3 Pritham Bigha to Samahuta		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber <i>partially</i>	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	140 Yes/No
f)	Contraction Joints provided or not (CC Pavement)	yes Yes/No
g)	Compaction of flank/slope & raincuts if any	No Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its paint	Sig S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U
c)	Condition of railings/slab/approach for Bridges	7 S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones Pavement road markings are provided and maintained	200m Yes/No yes
4.	Compliance History	
a)	Status of ATR's & any others	Bushes found both side of Road

Overall Rating :

Satisfactory (S)	☒
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 2.12.20
 AE
 (Signature)
 Kunturba

NAME: