

NABARD

FIELD INSPECTION REPORT

Date of Inspection : 05/01/2021		District: Samastipur	
Division : Samastipur		Length (km): 0.750 km	
Name of the Road: Samastipur block ke Bajipur Jel chaur PWD Path to Garuaia Rath ka Bache Ste Bag me Path Numan			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.: 32010100312	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	SAU	
b)	Condition of Surfacing	SAU	
c)	Riding Quality	SAU	
d)	Road Camber	SAU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	Nil	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Work in Progress.


06/01/2021
(Signature)

NAME: Virekanand
JE