FIELD INSPECTION REPORT

)ivis	(400)		Length (km): 1.880KM	r
-	e of the Road:	garmastpur -	tolg to Panchyat yel	ng _
	me/Programme:	MAINTENANCE	mmasy	
Package No.:		Road Id No.:		
Status of the Project: Work is a case of:		Ongoing Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
SI. N	0	Parameters to	be checked	Remarks
L	Divement			
a)	Road Junction	condition		S/U/
Ы	Condition of S	urfacing		S/V
c)	Riding Quality			stu
d) Road Camber				S/U
(*)		from defects suc ase of CC Pavement.	h as visible cracks, exposed	/es/No
f) Contraction Joints		ints provided or not (CC Pavement)	Yes/No
g) Compaction of		flank/slope & raincu	nts if any	Yes/No
2.	Cross Draina	ie.		•
a)	Condition of he	ead walls in Hume pi	pe culverts including its painting	SISRI
r)	Condition of Al	outment & Wing wal	lls, Slab in RCC culverts	S/SRIA
)	Condition of rai	lings/slab/approach	for Bridges	\$/SRIA
	Road Furniture	CDW	ork is in Progre	
	Whether sign be stones/Pavement	ooards/informatory/o road markings are p	cautionary Board/km & 200m provided and maintained	Yes/Ne
	Compliance His	forty	1 725 TV	
	Status of ATR's & any others			ry D
alle:	Rating :		. 10	0.0
an r	Carring .	Satisfactory (S)		
	ļ		equires Improvement (SRI)	
		Unsatisfactory (U)	Am as rimprovement (SKI)	
				·

NAME: - Ravi Rangan DESIGNATION: J. E