

FIELD INSPECTION REPORT

Date of Inspection:	05.01.2021	District:	Aurangabad
Division:	works div Aurangabad	Length(km):	2.502
Name of the Road:	R240 - Soladga road to Bahurda - 2.		
Scheme/Programme:	MAINTENANCE	Road Id No.:	
Package No.:	429		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	S
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	Yes/No	yes
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	yes
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	yes
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	-
c)	Condition of railings/slab/approach for Bridges	S/SR/U	-
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	yes
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SR)

Unsatisfactory (U)

"S"

NAME:

R. M. D.
05-01-21
J.E.

05.01.21
A. G. B. (Signature)