FIELD INSPECTION REPORT

Said Of H	ispection:	780.1	7	
		The state of the s	District: Patug,	
Name of	Domapu the Road: Ba	The second section of the second section of the second second section of the section of the second section of the section of the second section of the section of t	Length (km): 2,00 kg	The same of the sa
Scheme/I	rogramme:		Sudhaila	
Package	No.:	MAINTENANCE		and the
	the Project:	C. And Applications and the Contract of the Co	Road Id No.:	
Work is a case of:		Ongoing/Completed/Under Maintenance under Maintenance New Connectivity/Up gradation/ Maintenance		
Sl. No.	And the second s		- Tallice	maurtena
		Parameters to	be checked	Y
1	Pavement -		The state of the s	Remarks
a)	Road Junction condition			
b)	A STATE OF THE PROPERTY OF THE			S/H
	Condition of Surfacing			- \$/U
c)	Riding Quality			~S/H
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Jo	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	ge in the second		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			-S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnite	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)		C's & any others		

Overall Rating :

Satisfactory (S) Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	٦

SOMARU RAM)

NAME:

DESIGNATION: (SC SINGH)