FIELD INSPECTION REPORT

Date of	Inspection: 0	1/01/2021 Di	strict: Patua.		
Division: Danapus			Length (km): 0.55 KM		
Name o			to Neelkarth To	olg	
Scheme	/Programme:	MAINTENANCE			
Packag	e No.:		ad Id No.:		
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is	s a case of:	New Connectivity/Up gr	vity/Up gradation/ Maintenance		
Sl. No.	142	Parameters to be c	hecked	Remarks	
1:	Pavement-				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
e)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement) Yes/			Yes/No	
g)	Compaction of tlank/slope & raincuts if any			Yes/No	
2.,	Cross Drainage				
a)	1			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance His	story			
a)	Status of ATR's	& any others		and the first state of the second	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRIV
Unsatisfactory (U)	

32113

DESIGNATION:

13mg 1901/71

31km 7.1.21

(Signature)

A.E. Marass ISOMARO RAM