FIELD INSPECTION REPORT

Date of Inspection: 07/04/2024	District: Patre
Division: Danapur	Length (km): 1.50 kg
Name of the Road: N430 Mahader	Astran Madhopur road to Sundar Raik gh

MAINTENANCE Scheme/Programme:

Package No.: Road Id No.:

Ongoing/Completed/Under Maintenance under maint Status of the Project:

New Connectivity/Up gradation/ Maintenance Work is a case of:

SI. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/V	
b)	Condition of Surfacing	√SÆJ-	
c)	Riding Quality	SAU	
d)	Road Camber	√8/U-	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Xes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of tlank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	VS/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	√S/SRI⁄IL	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
(a)	Status of ATR's & any others	NO ATR	

Overall Rating

Satisfactory (S)	SV
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

By Singy) (SOMARU RAM)

(Signature)