

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - *Cryan sibhalcar*
2. Name of Block/Road - *pipra school to fotepur school tal.*

A. For Road

1. Damage Location/Chainage : *0.0021km, 0.0281km, 0.1101km, 0.311km, 0.611km*
2. Damage Length : *0.9391km (0.93975 km) 0.911km, 1.41km*
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : *Brick badd & local soil*
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : *0.9391km (0.93975 km)*
APPROX

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

[Signature]
21.12.20
Signature

(Name of Inspector)

EE
RWD work division
Muzaffarpur Galt-1

GENERAL ABSTRACT

Name of Road Pipra School to Fatepur School Tak

District Muzaffarpur

Block Katra

Division Muzaffarpur East-2

Length of Road (in Km) 1.582 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	9.951
2	Sand Filling <i>Earth work</i>	0.000 0.820
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	9.951 10.771
TOTAL COST OF PROJECT IN LACS =		9.951

say 9.95 Lakh
say 10.77 lac

[Signature]
JE
RWD

[Signature] 17.12.20
AE
RWD

[Signature]
EE
RWD

Technically approved for RS ^{10.77} ~~9.95~~ lakh (Rupees ~~ten~~ ^{seventy seven} ~~ten~~ ^{ten} lakh ~~ninety five~~ ^{thousand} only)

[Signature] 12.12.20
SE
RWD WORK circle
muzaffarpur