

FIELD INSPECTION REPORT

Date of Inspection : 08-01-21		District:	PATNA
Division : Masaurhi		Length (km):	1.39
Name of the Road: Beroz PMGSY Road to Mahua Bigha			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:			
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		S S/U
a)	Road Junction condition		S S/U
b)	Condition of Surfacing		S S/U
c)	Riding Quality		S S/U
d)	Road Camber		S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No Yes
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Dinesh choudhary
JE

(Signature)
08/01/21
(Signature)