

FIELD INSPECTION REPORT

Date of Inspection : 07-01-2021
 Division : DHAMDAHIA
 Name of the Road: KAJRA (Chandani Chowk) se Navtoliya.
 Scheme/Programme: MAINTENANCE
 Package No.: MM 654
 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/N
a)	Road Junction condition	✓
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/N
d)	Road Camber	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	S/S/N
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/N
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/S/N
c)	Condition of railings/slab/approach for Bridges	S/S/N
3.	Road Furniture	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

U

(Signature)
 07-01-2021

NAME: - PRAMOD KUMAR
 (T.O)