

ROAD INSPECTION REPORT

Date of Inspection: 17-12-2020 District: Patna.
 Division: Paliganj Length (km): 0.750 km
 Name of Road: SH78 road to Hirachak.
 Scheme: MAINTENANCE

Par: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work in case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a. Road Junction Condition:		✓
b. Condition of Surfacing:		✓
c. Riding Quality:		✓
d. Road Camber.		✓
e. Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ✓
f. Contraction joints provided or not (CC Pavement)		Yes/No
g. Compaction of flank/slope & raincuts if any		Yes/No
2. Cross Drainage		
a. Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b. Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c. Condition of railings/slab approach for Bridges		S/SRI/U
3. Road Furniture		
a. Whether sign boards/informatory/cautionary Board/km & 200m Stones/pavement road markings are provided and maintained		Yes/No ✓
4. Compliance History		
a. Status of ATR's & any others		

Overall Rating:

Satisfactory (S) ✓
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

 17/12/2020
 J.E.

 17/12/2020
 A.E.

(Signature)

NAME

DESIGNATION