## FIELD INSPECTION REPORT

		FIELD INSPEC	CTION REPORT	
Date of				
Date of Inspection: -29/12/20 District: - Argmic  Division: - Rew D(W) Mr F. B. Length (km): - 2.			Length (km): - 2-143 *	m
Name o	f the Road: -	miszapor to	manhohandy	
	Programme:	MAINTENANCE		
Package	e No.:		Rond Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance  New Connectivity/Up gradation/ Maintenance		
Work is a case of:		New Connectivity/C	op gradition wanternate	Remarks
Sl. No.		Parameters to	be checked	1. 1. 1. 1.
1.	Pavement	The state of the s	A Comment of the Comm	A 07/11
a)	Road Junction			<b>L</b> 5/U
				<b>1</b> 57U
b)	Condition of Surfacing			VS/U
c)	Riding Quality			V87U
d)	n 1 Combon			
	Whether free from defects such as visible cracks, expo			
e)	aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compartion of flank/slope & raincuts if any			
2	Care Designage			
The second state	The of head walls in Hume pipe culverts including its painting Volote o			
a)	Condition of head wans in Front PT  Condition of Abutment & Wing walls, Slab in RCC culverts  S/SRI/			₽8/SRI/U
b)	Condition of Abutment & Wing wans, Side in			S/SRI/U
c)	Condition of railings/slab/approach for Bridges  S/SR/O			
3.	Road Furnitu	re	Carlotte Commence of the	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
v	AND THE RESERVE OF THE PROPERTY OF THE PROPERT			
4.	Status of ATR'	s & any others		NO
a)	Status of ATK	o wany contra		

Overall Rating

		A
	Satisfactory (S)	5
49	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

NAME: