FIELD INSPECTION REPORT

Block-Garkha

Date of Inspection: 08.01.2021			District: Savan (chapres)		
Division: Chapre-1			Length (km): 2.00 km.		
Name of the Road: Horsh kadna to Scheme/Programme: MAINTENANCE				to Mithebur Brahm Sthan V	
			MMC34 (CEM)		
	age No.:		Road Id No.:		
Status of the Project:		Ongoing/Completed	Under Maintenance		
The same to be considered as the facility of the first of the same of the con-		New Connectivity/U	p gradation/ Maintenance		
SI. No		Parameters to	be checked	Remarks	
1.	Pavement			in Constitution	
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber		•	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No .	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b) .	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign b stones/Pavement	oards/informatory/ca road markings are pr	utionary Board/km & 200m ovided and maintained	Yes/No	
	Compliance His	tory to the		The state of the s	
1)	Status of ATR's	& any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:

(Signature)