FIELD INSPECTION REPORT Block- Nagra

Date o	f Inspection:	8.1.2021	District: Serran (cha	(prd)	
Division: detre-1			Length (km): 2-185 km.		
Name of the Road: TOS Nagre - Crarkha Path Chakmakho may					
Scheme/Programme: MAINTENANCE			Mancay (MB)		
Packag		Road Id No.:			
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance					
SI. No.	A. 2011年建	Parameters to	be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			^S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			`S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement) Ye			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainag	economic and and a			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furnitur	e de la companya de l			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
4	Gompliance H	story			
a)	Status of ATR's	& any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Signature)

NAME:

DESIGNATION: