## FIELD INSPECTION REPORT

Block- Magra

Date of Inspection:	8-1-2021 District: Savant	chapre
Division:		oun.
Name of the Road:	TOS Magra-Carkhe Posh from	n Candak Canal) To Rasw
Scheme/Programme:	MAINTENANCE mmc3y-wB	
Package No.:  Status of the Project: Ongoing/Completed/Under Maintenance		
Status of the Project: Work is a case of:		
Sl. No.		as Sage To Live Venich La
	Parameters to be checked	Remarks
1. Pavement		Activities and the second
a) Road Junction	Road Junction condition	
b) Condition of S	Condition of Surfacing	
c) Riding Quality	Riding Quality	
d) Road Camber	Road Camber	
<b>A</b> 1	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f) Contraction Joi	Contraction Joints provided or not (CC Pavement)	
g) Compaction of	Compaction of flank/slope & raincuts if any	
2. Cross Drainag	e majoriti.	
a) Condition of he	Condition of head walls in Hume pipe culverts including its painting	
b) Condition of Al	Condition of Abutment & Wing walls, Slab in RCC culverts	
	Condition of railings/slab/approach for Bridges	
3. Road Furnitur		And the second s
a) stones/Pavement	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4 Compliance His	ilory	The state of the s
a) Status of ATR's	& any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI.
Unsatisfactory (U)	

NAME:

**DESIGNATION:** 

(Signature)