

FIELD INSPECTION REPORT

Date of Inspection : 08/01/2021	District: muzaffarpur
Division : muz - East - 2	Length (km): 2.25 km
Name of the Road: 1049-103 NH 77 Rampur Han to Majlish Indheurb Chapra.	
Scheme/Programme: MAINTENANCE	P.M.U.S.
Package No.: BR-232-385	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No Required maintenance
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Required re-fixing & maintain
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

At many places road surface worn out in BTR e.e. shoulders & Road furniture require to be maintain.

(Signature)

08.1.2021
JE

NAME: Kamte del Singh

DESIGNATION: JE