

Date of inspection: 8/01/2022

District: Nalanda

Sl. No: 44/6A

Length: 3.2 KM

Name of the Road: NH-410 Utlar Chaturpur Bishahara to Chauri Chauri
Mabadih Chauri Chauri Road

Scale: 1:1000

Scale: 1:1000

Name of the Project: Road & Drainage

Consolidated
Under: 2019-2020

Name of the Officer: (Name of the Officer)

No. Parameters to be checked

Sl. No.

1. Pavement

2. Road surface condition

✓ S/U

3. Condition of Drains

✓ S/U

4. Road Quality

✓ S/U

5. Road Condition

✓ S/U

6. Whether free from defects such as visible cracks, expansion joints, etc. on the surface of C.C. Pavement

✓ Yes/No

7. Condition of joints provided under C.C. Pavement

✓ Yes/No

8. Condition of Bank Slope & rainwater (if any)

✓ Yes/No

9. Cross Drainage

10. Condition of head walls of stone pipe culverts including its painting

✓ S/SRI/U

11. Condition of Abutment & Wing walls, Slab in RCC culverts

✓ S/SRI/U - NA

12. Condition of railing & approach for Bridges

✓ S/SRI/U - NA

13. Road Furniture

14. Whether sign boards/informatory/cautionary Board/km & 200m

✓ Yes/No - NA

15. Whether pavement road markings are provided and maintained

16. Compliance History

17. Status of ATR & any others

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Signature
8/01/2022
(Signature)

Mr. Gayash Kumar Rajan