

Date of Inspection: 08/01/2021 District: Nalanda
 Division: H/1/5a Locality: 0.480 K.M.
 Name of the Road: Badimath to Murgawan Path to Gago Bigha Mahadali
 State of the Road: MAINTENANCE Tola via P.S. school Gago Bigha
 Project No.: 1222654 (SC) Road Id No.:
 Name of the Project: Ongoing Completed Under Maintenance - Under improvement
 ATR is a case of: New Connectivity Upgradation/Maintenance - New Connectivity

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
1.	Road Junction condition	S/U ✓
1.	Condition of Surfacing	✓ S/U
1.	Riding Quality	✓ S/U
1.	Road Camber	✓ S/U
1.	Whether free from defects such as visible cracks, exposed gravelation in case of CC Pavement	Yes/No ✓
1.	Curbs/kerbs provided or not (CC Pavement)	Yes/No ✓
1.	Compaction of Bank/slope & raincuts if any	✓ Yes/No
1.	Cross Drainage	
1.	Condition of head walls in Stone pipe culverts including its painting	S/SRI/U ✓
1.	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/UA.A
1.	Condition of railings/slab approach for Bridges	S/SRI/U - N.A.
1.	Road Furniture	
1.	Whether sign boards/informatory/cautionary Board km & 20m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
1.	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

08/01/2021

(Signature)

ME: Ganesh Kumar Ranjan