FIELD INSPECTION REPORT

Date of Inspection: 07-01-21			District: Benug		
Division: Banka-1			Length (km): 4.00		
Name of	the Road: Bis	hanpur Kothi	g to Ngnaychak mainathel	Loux	
	Programme:	MAINTENANC			
Package No.:			Road Id No.:		
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No.		Parameters	s tojbejcheckedj	Remarks	
1.	Pavement				
a)	Road Junction condition			8/U	
b)	Condition of Surfacing			√ S/U	
c)	Riding Quality			√ S/U	
d)	Road Camber			√8 /U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drain	ige:::::::			
a)	Condition of	S/SBA/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of	S/SRI/U	M		
3.	Road Furnit	ure		Andrews .	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	·Compliance	History			1000
a)		R's & any others			

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

9mmes 08/01/21 (Signature)

NAME: DHARMVEER KUMAR

DESIGNATION: JE