FIELD INSPECTION REPORT

		FIELD INSPECTI	ON REPORT	
ate of In	spection: - 2	112/2020 D	District: - Arama	
Division: rada awa			Length (km): 0.750 KM	
Vame of	the Road: _m	1. wair house to	md. Jahir house	
	rogramme:	MAINTENANCE		
Package	No.:	11	lond Id No.:	
Work is a case of: New Connecti		Ongoing/Completed/U	eted/Under Maintenance	
		Parameters to be checked		Remarks
Sl. No.		Parameters to be	eneckou	
1.	Pavement	in the hard	The state of the s	_8/U
a)	Road Junction	ion condition		√8/U
b)	Condition of Surfacing		V8/U	
c)	Riding Quality		√8/U	
d)	Road Camber			Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
	aggregates in c	es in case of CC Pavement.		
f)		Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any			
2.	Cross Drainage S/SRI/U			S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC curverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furnitu	ire	0.000	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance	History		NO
a)	Status of ATF	c's & any others		

Overall Rating

	ϵ
Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 5.6

14	A B	AT.	
	ΑN	ME:	