

# FIELD INSPECTION REPORT

Date of Inspection : 08.01.2021	District: Buxar
Division : Dumraon	Length (km): 0.450 km
Name of the Road: PCC Kharanviya to chimni Bhatauli Road	
Scheme/Programme: MAINTENANCE	GTSNY
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N/A
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	N.A.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Drop करने के लिए प्रस्ताव गाया है।

Vikash  
08/01/2020

(Signature)

NAME: Vikash Kumar

DESIGNATION: AE