FIELD INSPECTION REPORT

Date of Inspection:	8.1.2021	District: Savam (chapra)		
Division:	1p	Length (km): 0.85 km		
Name of the Road: LO22-Pahadpur				
Scheme/Programme:	MAINTENANCE	WWC3Y-NDB		
Package No.:		Road Id No.:		
Status of the Project:	Ongoing/Completed	Under Maintenance		
Work is a case of:	New Connectivity/U	Jp gradation/ Maintenance		
SI. No.	Parameters to	be checked Remarks		

SI. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	`s/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	`S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
а)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	Man Saint
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:

Scanned with CamScanner

(Signature)