FIELD INSPECTION REPORT

Date of In	spection: D(10112011 District: Malabud	
Division:	Bilions land Length (km): 1520 kg	
	ne Rand: Company Character Comments to Abad	lagarh
	rogramme: MAINTENANCE MMGLY BOTCE CALDO	
Package 1	No.: Road Id No.:	AH A
Status of	the Project: Ongoing/Completed/Under Maintenance	
Work is	rease of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked,	Remarks
1.	Pavement	1 - 1 - 1
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slame & minute is	
2	Cross Drainage	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S/SRI/U
3.	Road Furniture	1 3/3/(//0
a)	Whether sign boards/informatory/cautionary Board/km & 200r stones/Pavement road markings are provided and maintained	n Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	
		No

Overall Rating :

Satisfactory (S)	C
Satisfactory but requires Improvement (SRI)	>
Unsatisfactory (U)	-

(Signature)

NAME: Mojib Ahmad

DESIGNATION: 3.12