FIELD INSPECTION REPORT

Date of I	nspection: 09	1/01/2021	District: Halanda		
Division: Bihar sharit			Langella (lens) a 1 = 51		
Name of	the Road: HA	H-31 TO SJ	huli		
Scheme/	l'rogramme:	MAINTENANC			
Package			Road Id No.:		
	the Project:	Ongoing/Comple	eted/Under Maintenance		
	a case of:	New Connectivit	ty/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Rond Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drains	ge			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
14.	Compliance History			-	
a)	Status of ATE	t's & any others		NIL	

Overall Rating

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Binod Kumar Shipl DESIGNATION: J.E.