

FIELD INSPECTION REPORT

| | | | |
|------------------------|--|--------------|---------|
| Date of Inspection : | 9/1/021 | District: | Purnag |
| Division : | R.W.D. D.V. Purnag | Length (km): | 0.915-2 |
| Name of the Road: | NH 107 To Hat Tola | | |
| Scheme/Programme: | MAINTENANCE | | |
| Package No.: | | Road Id No.: | |
| Status of the Project: | Ongoing/ Completed /Under Maintenance | | |
| Work is a case of: | New Connectivity /Up gradation/ Maintenance | | |

| Sl. No. | Parameters to be checked | Remarks |
|---------|--|----------|
| 1. | Pavement | |
| a) | Road Junction condition | SAU |
| b) | Condition of Surfacing | SAU |
| c) | Riding Quality | SAU |
| d) | Road Camber | SAU |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | SA/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | SA/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | SA/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | |

Overall Rating :

| | |
|---|---|
| Satisfactory (S) | S |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME: MUMILAL DAS
DESIGNATION: J.E.

Mumilal Das
(Signature)