

FIELD INSPECTION REPORT

Date of Inspection :	06/01/2021	District:	Nalanda
Division :	Bihar Charif	Length (km):	2.810 km
Name of the Road:	East Beldaniya to Birhli Beldaniya via west Beldaniya		
Scheme/Programme:	MAINTENANCE	MMGSy	BRICS (NDB)
Package No.:		Road Id No.:	
Status of the Project:	<input checked="" type="checkbox"/> Ongoing/ <input checked="" type="checkbox"/> Completed/ <input type="checkbox"/> Under Maintenance		
Work is a case of:	<input checked="" type="checkbox"/> New Connectivity/ <input type="checkbox"/> Up-gradation/ <input type="checkbox"/> Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

(Signature)

NAME: Mojib Ahmed

DESIGNATION: J.E