

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District: Buxar	
Division : R.W.D Buxar		Length (km): 0.525 Km	
Name of the Road: Baskulha v Boratogaon Road to chauria ti Kurgak			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: m.m.G.S.Y	
Status of the Project: ☒ Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A S/U
b)	Condition of Surfacing	N/A S/U
c)	Riding Quality	N/A S/U
d)	Road Camber	N/A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ☒ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S/
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

REDMI NOTE 7 PRO
AI DUAL CAMERA

NAME:

(Signature)