

# FIELD INSPECTION REPORT

Date of Inspection : 7-1-2021	District:	Buxar
Division : R.W.D Buxar	Length (km):	0.455 Km
Name of the Road: Mathaulitola 3 TO pithaulitola 4 mungawtola.		
Scheme/Programme:	MAINTENANCE	
Package No.:	✓	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	mm.6.5y
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

7-1-2021

REDMI NOTE 7 PRO  
AI DUAL CAMERA

(Signature)