FIELD INSPECTION REPORT

	nspection : 🔥	101/2/	District: 40/2 3/2	
Division: 111-12/			Length (km): 0,758	
Name of	the Road:	102 9	(41/4) 4	
Scheme/l	Programme:	MAINTENANCE	MM (137 (5C)	
Package	No.:		Road Id No.:	
			d/Under Maintenance	
Work is	a case of:	New Connectivity/	Up gradation/ Maintenance	
SL No.	7.1.5	Parameters to	he checked	Remarks
1,	Payement		AMPSON EMET OF	
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			√s/U
c)	Riding Quality			√\$/U
d)	Road Camber			√\$/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2. '	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U			S/SRI/U
c)	Condition of railings/slab/approach for Bridges S/SR			S/SRI/U

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Overall Rating

a)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

Yes/No

NAME: SATISH CHAUDHARY

Road Furniture

Compliance History

Status of ATR's & any others

DESIGNATION: A. 2.

Scanned with CamScanner