

FIELD INSPECTION REPORT

Date of Inspection : 06/12/2020	District: East Champaran
Division : Motihari	Length (km): 1.041
Name of the Road: Piprakothi NH 28 to Mahito Tola	
Scheme/Programme: MAINTENANCE	PM65Y
Package No.: BR/112/558	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	"U"

7/12/2020
(Signature)

NAME: Anil Kumar Prasad Thakur

DESIGNATION: J.C.