

# FIELD INSPECTION REPORT

|                                                            |                                            |
|------------------------------------------------------------|--------------------------------------------|
| Date of Inspection : 06/12/2020                            | District: East Champaran                   |
| Division : Motihari                                        | Length (km): 1.296                         |
| Name of the Road: Pipra NH to Bankhurwa                    |                                            |
| Scheme/Programme: MAINTENANCE                              | PMGSY                                      |
| Package No.: BR/11R/561                                    | Road Id No.:                               |
| Status of the Project: Ongoing/Completed/Under Maintenance | ✓                                          |
| Work is a case of:                                         | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | <b>Pavement</b>                                                                                                      |             |
| a)      | Road Junction condition                                                                                              | S/✓         |
| b)      | Condition of Surfacing                                                                                               | S/U         |
| c)      | Riding Quality                                                                                                       | S/✓         |
| d)      | Road Camber                                                                                                          | S/✓         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No      |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No      |
| 2.      | <b>Cross Drainage</b>                                                                                                |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U N.A |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U N.A |
| 3.      | <b>Road Furniture</b>                                                                                                |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No      |
| 4.      | <b>Compliance History</b>                                                                                            |             |
| a)      | Status of ATR's & any others                                                                                         | Pending     |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | —   |
| Satisfactory but requires Improvement (SRI) | —   |
| Unsatisfactory (U)                          | "U" |

06/12/2020  
(Signature)

NAME: Anil Kumar Prasad Thakur

DESIGNATION: J.E