

FIELD INSPECTION REPORT

Date of Inspection : 10/12/20		District: East Champaran	
Division : Mithari		Length (km): 0.800 Km	
Name of the Road: LO67 RWD Road To Bodega			
Scheme/Programme: MAINTENANCE		PMUSY	
Package No.: RR-11R-574		Road Id No.: -	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New/Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRU/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRU/U	
c)	Condition of railings/slab/approach for Bridges	S/SRU/U N/A	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4. Compliance History			
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Rajendra Prasad Yadav

DESIGNATION: A.E

(Signature)

Rajendra Prasad Yadav
10/12/20

[Signature]
10/12/20