

FIELD INSPECTION REPORT

Date of Inspection : 29/12/20		District: East Champaran
Division : Motihari		Length (km): 1.50 Km
Name of the Road: Raulhanpur Sabha Nadiya Tola via Air Tola		
Scheme/Programme: MAINTENANCE		MMUSY
Package No.: —		Road Id No.: —
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SR/U ✓
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI ✓
Unsatisfactory (U)	


(Signature)
02/01/21

NAME: Baidyanth K.

DESIGNATION: J.E