

ROAD INSPECTION REPORT

Date of Inspection: 02/12/21 District: HALANDA
 Division: HILSA Length (km): 1.25 km
 Name of the Road: 702 Bhangar Bazar road to Chhara
 Scheme/Programme: MAINTENANCE
 Package No.: MMGSY Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up grading/ Maintenance

Sr. No.	Parameters to be checked	Rating
1.	Pavement	S
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	YES/NO
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	YES/NO
f)	Contraction Joints provided or not (CC Pavement)	YES/NO
g)	Compaction of flank slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in stone pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A - S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 100m stones/Pavement road markings are provided and maintained	YES/NO
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

(Signature) 07/11

ANJANI KUMAR
 NAME: