FIELD INSPECTION REPORT

Date of l	Inspection: 0	5/01/2021	District: Nalander.		
Division: Dihazshevzik			Length (km): 3.000 K.M.		
The state of the s			azi Rivez To Gongeha	K (UR8)	
	Programme:	MAINTENANCE			
Package		10 1 10 11	Road Id No.:		
			d/Under Maintenance Up gradation/ Maintenance		
	a case of:			Control of the Control	
Sl. No.		Parameters	to be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	*Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				

Overall Rating :

Satisfactory (S)	8
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 12321

· No

NAME: Mukesh Yadas

Status of ATR's & any others

DESIGNATION: 4.7.