

FIELD INSPECTION REPORT

Date of Inspection : 27/12/2020		District: Katihar
Division: RWD Manihari		Length (km): 1.221 Km
Name of Road: Lohy - Tor to Khajate Haf (VRG)		
Scheme/Programme: MAINTENANCE		PMGSY
Package No.:		Road Id No.:
Status of the Project: <input checked="" type="checkbox"/> On going/Completed/Under Maintenance		
Work is a case of : <input checked="" type="checkbox"/> New Connectivity/Up gradation/Maintenance		
Sl NO.	Parameters to be checked	Remarks
1	Payement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or no (CC Pavement).	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume Pipe culverts including its Pinting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N/A
3	Road Furniture	
a)	Wheather sing boards/informatory/cautionary Boad/Km & 200m stones/Pavement road markings are provided and Maintained	✓ Yes/No
4	Compliance History	
a)	Status of ATR's & any other	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: SATISH CHAUDHARY
DESIGNATION: AE.

Satish 27/12/2020
(Signature)