## FIELD INSPECTION REPORT

			25 las	
Date of Inspection: 15-12-2020			District: myzallospyr	
Division: Myzasthrbus East-2			Length (km): 3·15km	
Name of	the Road: Lo	127- 707 to sir		
Scheme/1	Programme:	MAINTENANCE	pmwy	
Package	No.:		Rond Id No.:	
Status of the Project: Ongoing/Completed			Inder Maintenance	
Work is	a case of:		gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks	
1.	Pavement	H. F. Land		
a)	Read Junction condition			√S/U -
b)	Condition of Surfacing			S/U√
c)	Riding Quality			√s/u
d)	Road Camber			√s/u
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
<b>b</b> )	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
ċ)	Condition of railings/slab/approach for Bridges			S/SRI/U+
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance I	listory		44

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	<u> </u>
Unsatisfactory (U)	U

haren korrs

Islizizo >0
(Signature)

NAME: GA NESH KUMAR

DESIGNATION: JUNIOR ENWHEER

Status of ATR's & any others